

<a href="#">Français</a>	<a href="#">Contact Us</a>	<a href="#">Help</a>	<a href="#">Search</a>	<a href="#">Canada Site</a>
<a href="#">Home</a>	<a href="#">About us</a>	<a href="#">Media room</a>	<a href="#">Environment</a>	<a href="#">Emergencies</a>
<a href="#">Air</a>	<a href="#">Marine</a>	<a href="#">Rail</a>	<a href="#">Road</a>	<a href="#">Major issues</a>

## Vehicle Recalls On-Line Database

### Details of Recall #: 2002201

To determine if your vehicle was involved in a recall and has not been corrected, you should contact the manufacturer providing the vehicle's make, model, year and serial number.

Make: <b>DODGE</b> Model: <b>CARAVAN</b> Affected Year(s): <b>1996 1997 1998</b> Units Affected: <b>240667</b>	TC Recall #: <b>2002201</b> Manufacturer: Campaign Code: <b>B24</b>
<b>Recall Details</b>	
On certain vehicles, the clockspring assembly may have been backwound during the vehicle assembly process. This could illuminate the air bag warning lamp and may eventually result in a driver's air bag open circuit. Correction: Dealers will replace the clockspring assembly on vehicles with less then 115 000 kms. Owners of vehicles with over 115 000 kms will be offered extended lifetime warranty on the clockspring.	

[« Previous Recall](#)

[Next Recall »](#)

[New Search](#)